

# BAI

#### RoboJackets

The Arthur M. Blank Family Foundation

2007 TE Sessions Fabrication and Safety

October 23, 2007

www.robojackets.org



Machinability



### What does machinability mean?

- Design your parts so they can actually be made
- No intersecting or interfering holes
- Parts fit together properly

Keys

- Good design discipline
- Keep records of designs and changes
- Make sure machinists are aware of changes!



Drafting



### What does drafting mean?

- Technical Drawings of parts to be fabricated
- Specify all relevant dimensions and tolerances
- Make drawing readable! Machinists can't read minds

Keys

- Dimension parts in only one unit (in. or mm)
- Don't overlap dimensions
- Callout hole sizes and threads
- Show 3 views of part (Top, Right, Front)











### Drafting Well drafted hole callouts







RoboJackets

YOKE 2X TAPPED HOLES DON'T NEED TO GO THROUGH ENTIRE BLOCK

BRIAN GUERRIERO 513-404-2310





# SAFETY





Safety



General

#### USE COMMON SENSE!! IF YOU HAVE TO THINK TWICE, ITS NOT SAFE!!!

#### **NEVER WORK ALONE**

**Rules** 

#### **OBEY THEM OR GET OUT**

Safety

- Accidents cause more than just pain
- Accidents will cause significant risk to your team
- Administration who hear about accidents will

try to shut you down



Safety



#### **Glasses vs. Face Shields**

Glasses protect your eyes in the direction you're looking Face shields double protection, plus protect from Sides, but not ok alone

Side shields must be worn on prescription glasses







Safety **Welding Masks** 



#### Welding masks must be worn while welding Shades are from 7-14 Higher number is darker Arc welding (TIG, MIG, Stick) – 10-14 shade Gas welding (Oxy-Act) – 7-10 shade







Safety Clothing & Hair



Shoes:

- BAD: sandals
- OK: soft shoes
- GOOD: boots
- BETTER: steel toed boots

**Clothing:** 

- BAD: tank tops and skirts
- OK: tee shirts and shorts
- GOOD: long sleeved shirts and pants
- BETTER: heavy snug shirts and jeans

Hair:

- BAD: long flowing hair
- OK: long hair pulled back
- GOOD: short hair
- BETTER: no hair



Safety **Gloves** 

**Plasic and Latex:** 

- Used for chemical handling
- Also used for sanitary issues

**Heavy Leather:** 

- Used for welding
- Also for handling hot material

Rubber lined fabric:

- Good for general use
- Keeps hands clean
- Protects from sharp edges







Safety **Ear Protection** 

# CAT

When to use:

- Grinding on steel (especially thin gauge)
- Using air tools

Ear Plugs:

- Comfortable
- Cheap
- Easy to use
- Effective

Ear Covers:

Roboleckers

- Bulky
- Effective
- Worn over ears









Dangers:

- Fumes
- Overspray

**Protect:** 

- Eyes (glasses)
- Mouth (mask)
- Skin (gloves)

Spills:

- Alert a teacher
- Make sure air is safe
- Sop up with litter or sawdust









Dust:

- Sanding and cutting wood, plaster or drywall creates dust
- Fine particles are suspended in air

**Protection:** 

- Dust masks must be worn
- Dust inhalation will cause respitory damage

**Prevention:** 

- Cut outdoors!!
- Vacuum
- Moisture (wet sanding)



Safety



**Moving Parts** 

- Don't touch any moving parts
- Spinning bits are very sharp

Fingers:

- Fingers are easily cut and ripped off by blades
- Keep your fingers AWAY from sharp objects

Maturity:

- No horseplay in the shop
- No throwing tools
- No fighting



Safety

**Pinch Points** 

- Some machinery parts will pinch
- You can become caught in a machine
- Wear proper clothing

Fingers:

- Keep fingers away from pinch point dangers
- Be Alert!





Safety

**Hot Parts** 

- Machined parts will be hot!
- Especially after cutting and grinding

Gloves

- Wear appropriate gloves when handling hot parts

#### Tools

- Drill bits get hot too!
- Chips are also hot
- Quench in water to cool parts down







Safety

Fixturing

- Make sure workpieces are affixed to the tool
- Use a vise or clamps

Vibration

- Proper fixturing prevents inaccuracies caused by

vibrations

#### Danger

- Improperly fixtured parts can fly out of clamp and cause injuries











Injuries

- Call for help
- Get the First Aid kit

When to call for help

- Notify an adult or teacher immediately
- Don't hesitate to dial 911

**First Aid Kit** 

- Must be located in an open, accessible area
- Make sure it is stocked
- Know where it is









Bleeding

- Apply pressure
- Wrap with a clean bandage
- Go to ER if bleeding does not stop

#### Shock

- Massive blood loss will cause shock
- Body's defensive mechanism
- Keep person warm and awake
- Dial 911

#### Fire

- Know where your fire extinguisher(s) are
- Make sure they are charged
- Don't hesitate to use it!!!







- If person is unconscious call 911
- Don't move them, will cause worse injuries

**Broken bones & joints** 

- Area will swell massively and be very painful
- Call 911
- Don't move the person or body part until help arrives

**Sprains and strains** 

- Don't move the joint
- Put ice on the swelling
- Ibuprofen (Advil) will help pain and swelling
- Keep weight off of injury







### **15 MINUTES**

- **1. Where is your First Aid Kit?**
- 2. What's in it?

- 3. Where is your fire extinguisher?
- 4. What other safety equipment do you have?





# FABRICATION





### Fabrication Basics



- Make sure drill bits are spinning the right direction (clockwise)
- Use sharp bits

Safety

- Eye protection is always required

**Common Sense** 

- If you don't think it's a good idea, don't do it!!!





### Fabrication Drilling



#### Drilling

- Drill bits remove material quickly
- Drill bits are not precise

Lubrication

- Drilling creates a lot of heat and friction
- Oil helps disperse heat and protect bits
- Always use oil while drilling in metal





### Fabrication Drilling



#### Speed and Bit size

ALUMINUM: 800-1000 RPM STEEL: 300-800 RPM

- As drill bit size increases, cutting speed must decrease
- Increased bit diameter requires more power to turn
- Chips
- Watch chip formation
- Nice long chips are good
- Squeaking means speed too high and not enough oil





## Fabrication

Drilling

DEWALT

- Two types
- Handheld Drills
- Drill Presses

#### Handheld Drills

- Convenient
- Easy to use
- Battery or corded
- Inaccurate



#### **Drill Presses**

- Restrictive to parts that can fit
- Powerful
- Accurate



### Fabrication Drilling



- Center punch your marks before drilling
- Drill pilot holes
- Step up drill bit sizes to make a large hole
- Ex. ½" hole:

**Center punch mark** 

Drill  $\frac{1}{4}$ " hole, then 3/8", then  $\frac{1}{2}$ "

#### Thick material

- Peck drill
- Drill a little bit, pull out
- Keep oil in the hole
- Don't let drill bit get too hot

Large bits ( >  $\frac{1}{2}$ ")

- Use only in lathe or mill
- Bits are too big for handheld drills
- Material removal rate too high for

drill press



### Fabrication Drilling









### Fabrication Cutting



Cutting

0107

- Material is removed along direction of blade travel
- Powered and Manual

Manual (Hacksaw)

- Simple & quick
- Can be accurate if part is fixtured properly
- Safe

**Powered (Bandsaws and Circular saws)** 

- Quick
- Accurate
- Dangerous



### Fabrication Cutting



#### **Materials**

- Cut metal, plastic or wood

Metal

- Aluminum: Toothed blades only
- Steel: Abrasive blades

#### Plastic

- Large toothed blades







### Fabrication Cutting

**Rotary Saws** 

- One round blade with multiple teeth
- Toothed or abrasive

Chop saws

- Blade is moved into the fixed workpiece

Table saws

- Plastic and wood only
- Workpiece is moved into spinning blade







# Fabrication

Cutting

#### Milling

- Good for cutting thick plates

Shears

50

007

- Good for cutting thin plates

Hacksaws

- Good for quick cuts

**AA** 







# Fabrication

#### Cutting









### Fabrication Grinding



Why Grind?

- Grinding removes a small amount of material
- Leaves a smooth surface finish
- Creates a lot of heat

Surfaces

- Grinding surfaces are like thousands of small saw teeth
- Sandpaper, stone, or files

Rated in "Grit"

- Higher number means finer grinding surface
- Lower number means more material can be removed





### Fabrication Grinding



#### Grinders

- Benchtop
- Handheld

**Bench Grinders** 

 Workpiece is ground in the spinning wheels of the stationary tool

**Angle and Die grinders** 

- Handheld tools grind on stationary workpiece
- Can also be used to cut steel with cutting disc




## Fabrication Grinding

Safety

- Eye and ear protection
- Face shield

**Steel and Aluminum** 

- Do not grind aluminum
- Aluminum melts and sticks to grinding wheels





# Fabrication









**Reasons to Mill** 

- Material removal
- Accurate hole placement
- Multi-axis machining

**Types of Mills** 

- Vertical (most common)
- Horizontal

#### Tooling

- Endmills
- Facing bits
- Drills & Reams









#### Basics

- Tool remains stationary
- Workpiece moves with table
- x,y,z axes

#### CNC

- Computer Numeric Control
- Allows precise shapes to be cut quickly

Precision

- Properly fixtured parts can be machined up to 0.0005" accuracy

 Material removal rates must be controlled to maintain precision





#### Endmills

- Cut vertically or horizontally
- High material removal rates

Facing tools

- Remove uniform layer of material from horizontal surface

Reams

0107

- Create an accurate hole diameter from a drilled hole
- Slow











## Fabrication Turning

**Reasons to Turn** 

- Material removal
- Accurate round parts
- Make couplings
- Cut threads

#### **Types of Lathes**

- Metal
- Wood

GA

#### Tooling

- Turning inserts
- Parting bits
- Single point cutting bits
- Drills & Reams



#### Fabrication Turning



#### Terminology

- Chuck
- Toolpost
- Tailstock
- Saddle
- Crossfeed
- Center

#### Gearing

- Lathes are geared to cut threads at a certain distance per revolution
- Constant feed rates provide good accuracy and surface finish





## Fabrication Turning







## Fabrication Tapping



**Reasons to Tap** 

- Cut threads inside a hole
- Screw pieces together

Tap sizes

- Thread size is nominal diameter of bolt
- Also measured by Threads Per Inch
- Ex: <sup>1</sup>/<sub>4</sub>" x 20, <sup>1</sup>/<sub>4</sub>" x 28
  - 1/4" bolt, 20 threads per inch
  - 1/4" bolt, 28 threads per inch

Lubrication

- Always oil taps
- Slow cutting produces a lot of friction



# Fabrication Tapping



How to Tap

- Drill the proper hole
- Consult tap table
- Turn tap 2-3 rotations
- Reverse direction to break chips inside hole
- Turn 1-2 turns, reverse 1/2 turn, repeat







## Fabrication Tapping













## **45 MINUTES**

- 1. Design a coupling
- 2. Connect this motor shaft to this gear shaft
- 3. Detail the machining processes involved
- 4. Draw and dimension your design









Legal



These slides and more are available at

http://www.robojackets.org

All media included is either in the public domain, generated by the author/s or covered by Fair Use of Copyrighted Material for Educational Purposes Title 17 Chapter 1 § 107 (which is reproduced in the next slide).

> For more information contact the RoboJackets. (contact info available via the web)





Legal



Title 17 Chapter 1 § 107. Limitations on exclusive rights: Fair use

Notwithstanding the provisions of sections 106 and 106A, the fair use of a copyrighted work, including such use by reproduction in copies or phonorecords or by any other means specified by that section, for purposes such as criticism, comment, news reporting, teaching (including multiple copies for classroom use), scholarship, or research, is not an infringement of copyright. In determining whether the use made of a work in any particular case is a fair use the factors to be considered shall include—

- (1) the purpose and character of the use, including whether such use is of a commercial nature or is for nonprofit educational purposes;
- (2) the nature of the copyrighted work;
- (3) the amount and substantiality of the portion used in relation to the copyrighted work as a whole; and
- (4) the effect of the use upon the potential market for or value of the copyrighted work.

The fact that a work is unpublished shall not itself bar a finding of fair use if such finding is made upon consideration of all the above factors.

